

One Islington Plaza Devon Street, Liverpool, L3 8HA

Whats New?

Under floor draining 100% Installation of beam and block floors 90% Mechanical & electrical works are progressing well on all floors Floors 6 to 10 – 80% of internal plasterboard installed Floors 2 to 5 – 75% of steel partitioning installed Installation of SFS board 100% Progression of roof installation

Works Scheduled

Completion of beam & block floors and gas membranes Commencement of roof parapet of roof installation Progression of mechanical & electrical works to all floors Progression of internal plasterboard throughout Progression of cladding package

Building Control

Building control last visited site of 9th May 2018. The inspector confirmed that they were content with the installation of the internal partitions, and that they were attending a Hilti demonstration on site within the next couple of week to look at fire stopping products. No adverse comments were raised.

Warranty Provider

Meridian visited site on 30th May 2018. Some minor remediation requirements were identified. The main contractor carried out these remediations and submitted to Meridian on 14th June 2018. EPCL have received confirmation from Meridian this item has now been sufficiently rectified by the main contractor.

If you need any further information in the meantime, please call us at the following offices:

Liverpool +44 (0)151 808 1250 London +44 (0)207 100 4141



